Peiting, 28/04/2025

Confirmation of RoHS Conformity

Dear Madam and Sir,

We hereby confirm and warrant that our products, see Table 1, comply with RoHS 2011/65/EU and its amendments of the delegated directive EU 2015/863 are compliant. Products, which are not RoHS compliant, see table 2.

The following substances are not intentionally used or added.

Chrom VI	0,1 Gew.%
Cadmium	0,01 Gew.%
Quecksilber	0,1 Gew.%
Blei	0,1 Gew.%
Polybromierte Diphenylether (PBDE)	0,1 Gew.%
Polybromierte Biphenyle	0,1 Gew.%
Di(2-ethylhexyl)phthalat (DEHP)	0,1 Gew.%
Butylbenylphthalat (BBP)	0,1 Gew.%
Diisobutylphthalat (DIBP)	0,1 Gew.%

We regret that due to the number of inquiries we have received and the complexity of each questionnaire, we are unable to reply to each individual request. We appreciate your understanding in this matter and trust that this letter will be sufficient in meeting your concerns.

For customized connectors (products not listed in Table 1), please contact customer service at sales@ept.de or Tel. +49 (0) 8861/2501-0.

Your sincerely
ept GmbH

i.A. S. Scholl
Product Administration

ept GmbH

Bergwerkstr. 50
D-86971 Peiting

Tel. +49 (0) 88 61/25 01-0
Fax +49 (0) 88 61/55 07
E-Mail: sales@ept.de
http://www.ept.de

Rechtsform: GmbH
Sitz der Gesellschaft: Peiting, Germany
Registergericht:
AG München, HRB 151797
Geschäftsführer:
Thomas Guglhör, Philipp Hoßfeld

Bankverbindungen:
Sparkasse Allgäu
BLZ 733 500 00
Kto.-Nr. 310 512 744
DE84 7335 0000 0310 5127 44
BIC BYLADEM1ALG

Deutsche Bank Augsburg
BLZ 720 700 01
Kto.-Nr. 0 468 447
DE50 7207 0001 0046 8447 00
BIC DEUTDEMM720

Commerzbank Memmingen
BLZ 731 400 46
Kto.-Nr. 730 3837
DE23 7314 0046 0730 3837 00
BIC COBADEFF

Ust.-ID-Nr. DE 267 715 283
Steuer-Nr. 125/115/30065

CERTIFIED ACCORDING TO
ISO 9001 • IATF 16949
ISO 14001 • ISO 50001
www.ept.de/certification

Zero8 SMT Board-to-Board-Applications with ScaleX technology Part No.	**RoHS complaint**	**Exeption**
405-51xxx-51; 405-52xxx-51; 405-53xxx-51; ;405-54xxx-51; 405-55xxx-51; 406-51xxx-51; 406-52xxx-51; 406-53xxx-51; 406-54xxx-51	Yes	none
Colibri® - HighSpeed SMT-Connectors COM Express® Part No.	**RoHS complaint**	**Exeption**
401-51xxx-51; 401-55xxx-51; 401-51xxx-52;401-55xxx-52; 402-51xxx-51; 402-51xxx-52	Yes	none
One27 SMT Board-to-Board Part No.	**RoHS complaint**	**Exeption**
403-51xxx-51; 403-52xxx-51; 403-53xxx-51; 403-54xxx-51; 404-51xxx-51; 404-52xxx-51; 404-53xxx-51; 404-54xxx-51; 404-59xxx-61; 413-52xxx-51; 413-53xxx-51; 414-52xxx-51; 414-53xxx-51	Yes	none
One27 SMT Board-to-Board with ribbon Cable Part No.	**RoHS complaint**	**Exeption**
404-61NN-LLL-xxx-1; 404-62NN-LLL-xxx-1; 404-64NN-LLL-xxx-1; 404-66NN-LLL-xxx-1	Yes	none
Connector straight according to IEC 60603-2 (DIN 41612) Part No.	**RoHS complaint**	**Exeption**
101-400x5; 101-8x1x5; 101-9x1x5; 102-4xxxx; 102-4xxxxTH; 102-6xxxx-0x; 102-7xxxx-0x; 102-8x2xx; 102-8xxxxTH; 102-9xxxx: 102-9xxxxTH; 103-4xxx5; 103-4xxx7; 103-8xxx5; 103-9x1x5; 104-4xx4; 104-4xxx5; 104-6xxxx-0x; 104-7xxx-0x; 104-9xxxx-0x; 104-9xxxx-0xTH; 105-4xxx6; 106-6xxxx; 106-4xxxx; 106-4xxxx; 107-4xxx6; 108-6xxxx; 109-4xxx5; 110-4xxxx; 110-6xxxx; 112-4xxxx; 112-6xxxx; 113-4xxxx; 114-4xxxx; 115-4xxxx; 115-4xxxx TH; 115-6xxxx; 115-7xxxx; 115-8xxxx; 115-8xxxx; 115-9xxxx; 119-9xxxx; 119-9xxxx TH; 124-4xxxx-00; 124-6xxxx:00; 124-8xxxx-00; 302-6xxxx-0x; 302-4xxxx-0x; 302-4xxxx-0xTH; 304-4xxxx-0x; 304-4xxxx-0xTH; 304-6xxxx-0x; 304-7xxxx-0x; 304-8xxxx-0x; 304-8xxxx-0xTH; 304-9xxxx-0x; 304-9xxxx-0xTH; 306-6xxx-1x; 315-15xxx; 315-15xxx	Yes	none
Connector straight according to IEC 60603-2 (DIN 41612) with punched Board-Lock Part No.	**RoHS complaint**	**Exeption**
xxx-xxxxxC1; xxx-xxxxxC2; xxx-xxxxxC3; xxx-xxxxx-xxC1; xxx-xxxxx-xxC2; xxx-xxxxx-xxC3	Yes	none
Connector angled according to IEC 60603-2 (DIN 41612) Part No.	**RoHS complaint**	**Exeption**
101-6xxx4; 101-6xxx5; 101-7xxxx; 101-400x4; 101-400x4TH; 101-7xxxx6; 101-8x0x4; 101-8x0x4TH; 101-8xxx6; 101-9xxx4; 101-9xxx4TH; 101-9x0x5; 101-9xxx6; 103-4xxx4; 103-4xxx4TH; 103-4xxx7; 103-6xxx4; 103-6xxxx5; 103-7xxx6; 103-8xxx4; 103-8xxx4TH; 103-8xxx6; 103-9xxx4; 103-9xxx4TH; 103-9xxx6; 105-4xxx4; 107-4xxxx4; 107-4xxx5; 109-4xxx4; 109-4xxx4TH; 111-4xxxx; 113-4xxxx; 116-4xxxx; 116-4xxxxTH; 116-6xxxx; 116-8xxxx; 116-8xxxxTH; 116-9xxxx; 116-9xxxxTH; 117-4xxxx; 120-4xxxx; 120-9xxxx; 123-4xxxx-00	Yes	none
Connector angled according to IEC 60603-2 (DIN 41612) with rotating Board-Lock Part No.	**RoHS complaint**	**Exeption**
xxx-xxxxxC1; xxx-xxxxxC2; xxx-xxxxxC3; xxx-xxxxx-xxC1; xxx-xxxxx-xxC2; xxx-xxxxx-xxC3	Yes	6c Lead in copper alloy Board-Lock (rotating part)
EC.8 SMT – High Speed Edge Card Connector Part No.	**RoHS complaint**	**Exeption**
408-52xxx-00x-11; 408-52xxx-00x-12; 408-52xxx-10x-11; 408-52xxx-10x-12	Yes	none
Flexilink board-to-board; Flexilink jumper Part No.	**RoHS complaint**	**Exeption**
990-52XNNxxx-110; 990-51NNxx-110; 991-50xx00-11	Yes	none
VarPol pin header and socket connectors; PC/104, PC/104-Plus Part No.	**RoHS complaint**	**Exeption**
961-60xxx-xx; 961-40xxx-xx; 962-40xxx-xx; 962-60xxx-xx; 964-60xxx-xx; 964-40xxx-xx; 964-61xxx-xx; 971-xx0xx-xx; 972-xx0xx-xx; 981-xx01x-xx; 982-xxxxx-xx; 962-17xxx; 272-300xxx-31; 264-1x302; 278-0x4xx-51	Yes	none
MicroTCA®; AdvancedTCA Artikel-Nr.	**RoHS complaint**	**Exeption**
501-50096-183; 502-50096-183; 512-50500x-163	Yes	none
AdvancedTCA® HighSpeed Signal- and Power Connectors Part No.	**RoHS complaint**	**Exeption**
511-5050x-1x3	Yes	6c Lead in copper alloy Board-Lock (rotating part)
hm2.0 Hardmetric 2mm for Backplane Systems CompactPCI Part No.	**RoHS complaint**	**Exeption**
243-1xxxx-15; 243-2xxxx-15; 243-3xxxx-15; 243-4xxxx-15; 243-5xxxx-15; 243-6xxxx-15; 245-1xxxx-15; 245-2xxxx-15; 245-3xxxx-15; 245-6xxxx-15; 244-1xxxx-15; 244-2xxxx-15; 244-3xxxx-15; 244-5xxxx-15; 244-6xxxx-15; 246-1xxxx-15; 246-2xxxx-15; 246-3xxxx-15; 246-6xxxx-15	Yes	none
Velox® - Highspeed Backplane Part No.	**RoHS complaint**	**Exeption**
308-50xxx-42; 308-51xxx-42; 308-52xxx-42	Yes	none
Power Terminals Part No.	**RoHS complaint**	**Exeption**
910-22xxx; 911-32xxx; 911-33xxx	Yes	none
910-60xxx	Yes	6c Lead in copper alloy (Nut)

table 1

Velox® - Highspeed Backplane Part No.	**RoHS complaint**	**Exeption**
308-50xxx-41; 308-51xxx-41; 308-52xxx-41	No	SnPb surface on press-fit zone

table 2